Connection example 6

Connecting KNX devices

If the green LED on the circuit board is to light up, insert the fuse and set the jumper to 24V.
The orange wire of the CAT cable must then, of course, be fitted with a terminal or similar.

